Ameren Missouri Pay As You Save Program

Rebates valid between January 1 and December 31, 2025.

Pay As You Save Rebate Measures (AHRI rated)	Rebate
Heating and Cooling Rebates*	
Mini-Split Air Conditioner or Heat Pump — 19+ SEER2	\$500 per ton
ASHP Dual Fuel – 15.2+ SEER2	\$2,000 per system
Central Air Conditioner – 15.2+ SEER2	\$1,000 per system
Air Source Heat Pump Replacing Air Source Heat Pump – 15.2+ SEER2	\$2,000 per system
Air Source Heat Pump Replacing Electric Resistance — 15.2+ SEER2	\$2,000 per system
Air Source Heat Pump (No Existing Central System) — 15.2+ SEER2	\$2,000 per system
Ground Source Heat Pump Replacing Ground Source Heat Pump — 23+ EER2	\$5,000 per system
Smart Thermostat — ENERGY STAR® or on Approved List	\$250 per thermostat

Weatherization [†]	
Air Sealing	\$0.06 per sq. ft.
Ceiling/Attic Insulation	\$0.20 per sq. ft.
Duct Sealing/Repair	50% of costs up to \$250 per home
Air Sealing (Infiltration Reduction)	\$0.06 per sq. ft.

Air Sealing – Seal and reduce air leakage. Areas may include but are not limited to:

- Attic penetrations and top plates
- Crawl space penetrations
- Penetrations under sinks
- Interior equipment closets
- Doors and windows
- Light switch/plug covers

Duct Sealing/Repair — Seal and repair exposed duct system to improve a home's ventilation rate.

Ceiling/Attic Insulation – Installation of blown-in cellulose insulation to a minimum of R-38 (R-value). Insulation marked with R-sticks beginning at the air barrier.

To be eligible for HVAC or weatherization rebates you must participate in tier 4 of the PAYS program. Rebates will reduce the total cost of the upgrades. Must have lived in the home for the past 12 months to allow for a usage analysis.

'HVAC: At least one of the following conditions: the AC unit was installed at least 10 years prior to the program appointment, AC efficiency is rated 14 SEER or less, and the AC is no longer working.

†Air Sealing: Must be able to achieve a 20% leakage reduction. Duct Repair/Sealing: Must be able to achieve a minimum of 20% leakage reduction.

Attic/Ceiling Insulation: Must have a beginning R-value of 20 or below with a minimum increase to R-38.





08/2025