

### Assessment Monitoring Reflects High Percentage of Compliance

Monitoring Parameters	Labadie Energy Center	Rush Island Energy Center	Sioux Energy Center	Meramec Energy Center
	LCPA	RCPA	SCPA	MEC Units
Percent of Assessment Monitoring Parameter Compliance	<b>96%</b>	<b>94%</b>	<b>96%</b>	<b>95%</b>
Percent of Assessment Monitoring Parameter Results Requiring Corrective Action	<b>4%</b> Molybdenum	<b>6%</b> Molybdenum Arsenic	<b>4%</b> Molybdenum	<b>5%</b> Molybdenum Arsenic Lithium