

McLean County Reliability REVIEW



July 2020



McLean County Reliability Project
370 Main St.
Decatur, IL 62523

INSIDE THIS ISSUE

- Local Vendor Spotlight
- Project Updates
- Ameren COVID 19 Response

LOCAL VENDOR SPOTLIGHT



CONSTRUCTION

L. Keeley is the civil contractor on the McLean County Reliability Project. L. Keeley was founded in 1976 as a family-owned paving company. Over four decades later, L. Keeley has become a nationally-known, full-service construction company with four diverse business groups – civil, paving, building and industrial.



CONNECT
WITH US



mcleancountyreliabilityproject.com



309.319.7186



mcleancountryreliabilityproject@ameren.com

PROJECT UPDATES

Construction is officially underway as crews have begun pouring foundations for the Normal East Substation. Access points in the project area are also being built to create entrances along the route corridor for the installation of structures.

You may notice added noise, traffic and equipment vehicles in or around the project area as our construction activities occur through 2020. Our goal is to create a safe work environment through the completion of this project. The safety of you, your community and our project team remains our top priority. Please maintain a safe distance from work sites and construction equipment as our crews operate equipment and continue to social distance.

AMEREN COVID-19 RESPONSE

As crews work to ensure we meet the continued energy needs in the region, they are implementing additional precautionary measures in an effort to mitigate the risks associated with COVID-19.

- Health screening questionnaire for contract partners who may have traveled outside of the region
- Work schedules have been modified to maximize time delay in work areas between work crews
- Wearing face coverings and social distancing where possible
- Additional hand washing stations have been added at each site

CAUTION

Please practice
SAFE SOCIAL DISTANCING
while crews are working.

Our families thank you!



TIMELINE

Data
Collection & Analysis

COMPLETE

Preliminary Engineering

COMPLETE

File
Certificate with ICC

COMPLETE

ROW & Field
Surveys

Nearly
COMPLETE



Construction

2019-2020

Substation

Fall '19 - Fall '20

Access, clearing and ground
survey

Spring '20

Foundations

Spring-Summer '20

Structure assembly and setting

Spring-Summer '20

Wire stringing

Fall '20

In-Service

DECEMBER 2020

To view an interactive project map go to:
<http://mcleancountyreliabilityprojectresources.com/interactivemap/>